




## Oslo 1600



x 2




= 60 MIN












Update: 2025/08/13

<http://www.norstone-design.com>






|                                                                                                           |                                                                                                  |                                                                                                           |                                                                                                                    |                                                                                                                      |                                                                                                            |
|-----------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------|
| <b>Ax34</b><br>          | <b>Bx34</b><br> | <b>Cx14</b><br><br>5x40 | <b>Dx40</b><br><br>4x40         | <b>Ex36</b><br><br>8x30           | <b>Fx24</b><br><br>4x15 |
| <b>Gx16</b><br><br>M6x15 | <b>Hx4</b><br>  | <b>Ix1</b><br><br>4mm   | <b>Jx20</b><br><br>Black or Oak | <b>Kx14</b><br><br>Green or White | <b>Lx2</b><br>          |
| <b>Mx6</b><br><br>3.5x16 | <b>Nx4</b><br>  | <b>Ox4</b><br>          | <b>Px2</b><br>                  |                                                                                                                      |                                                                                                            |



3



Cx4




Ex6



Ix1



4



Ax4



Ex4




Bx4




Kx4



1



2



3




5

Ax10


Ax4

This diagram illustrates the fifth step of the assembly process. It shows the side panel being attached to the cabinet frame. The side panel is positioned on the left, and the cabinet frame is on the right. The side panel is secured to the frame using four screws, labeled 'Ax4'. The screws are inserted into the pre-drilled holes in the side panel and tightened against the frame. The diagram also shows the top and bottom panels of the cabinet, which are already attached to the frame. The side panel is shown in a slightly offset position to demonstrate its placement relative to the frame.




7




8



9




10



11


Ax16



x4

12


Dx8



x4

13


Dx16



x4

14

Dx16




x4

15

Bx16




Jx16



x4


16

Hx4




x4


17





18



19



20



Lx2