


X01 transmitter

AIAIAI TMA-2 Product Manual

General

- **Power on:** Push button (3 sec).
- **Power off:** Push button (3 sec).
- **Enter pairing mode:** Double push button (power on).
- **Hard reset device:** Push button (7 sec).



LED FEEDBACK

State	LED
General	
Power on	Solid light (3 sec) matching battery level:
Turned on, idle and no link	Blinking LED 1, (1 sec on, 1 sec off)
Turned on, idle and linked to H10	Solid light LED 1
Power off	No feedback
Enter pairing mode	All LEDs blinking (300 ms on, 300 ms off) loop
Reset pairing mode	No function
Hard reset device	5 short flashes on all LEDs (< 0.5 sec on < 0.5 sec off)

LED battery level indicator

- **<25% battery:** LED one flashes.
- **25-50% battery:** LED one-two static.
- **50-75%:** LED one-two-three static.
- **75-100%:** All LEDs static.